




PSC 1/20 Interior stairs and studs



PSC 2/20 Layup of shower enclosures



PSC 2/20 Interior finishes at bunk area



PSC 2/20 Temporary closure of apparatus bays



PSC 3/20 View from east ongoing site work



PSC 3/20 Upper administration area



PSC 3/20 Apparatus bay mezzanine area



PSC 3/20 Apparatus bay



FS#2 3/20 Beginning excavation at FS#2




PSC 4/20 Kitchen area



PSC 4/20 Elevator installation



PSC 4/20 Training tower



PSC 4/20 Elevator installation



PSC 4/20 Apparatus bay doors installation



PSC 4/20 Bathrooms



FS#2 4/20 Excavation for FS#2



PSC 5/20 Rear garage bays



PSC 5/20 Monopole installation



FS#2 5/20 Beginning foundations at FS#2



PSC 6/20 Site work at Chestnut street entry



PSC 6/20 Finishes Day room



FS#2 6/20 Investigation for contaminated soils




PSC 7/20 Apparatus bay



PSC 7/20 Dispatch installation



PSC 7/20 Waiting are completion



PSC 8/20 Apparatus bay completion



PSC 8/20 Chestnut Street entry complete



FS#2 8/20 Continuing foundation & perimeter walls



PSC 9/20 West elevation of new Public Safety entry on the left and existing old Public Safety on the right



PSC 9/20 Rear elevation with existing old public safety in foreground (on the left)



FS#2 9/20 Start of masonry